

PROJECT PROFILE

PROJECT:
Tenth Ward Planters
Salt Lake City

COMPLETION DATE:
Summer 2004

OWNER:
The Church of Jesus Christ of
Latter-Day Saints - Salt Lake City

Facility:

The Tenth Ward building's planters are constructed of sandstone blocks topped with pre-cast concrete caps.

Problem:

The planters were leaking water, which was causing freeze-thaw damage to the sandstone exterior.

Solution:

CRS excavated the planters, cleaned the walls, and installed a high-quality membrane and protection board. The sprinkler system was then reinstalled, the planters were back-filled, and the original plants were replanted. CRS maintained access to the Tenth Ward building for the duration of the project.

TOP: Freeze-thaw damaged sandstone blocks (note sandstone fragments in foreground). CENTER: Waterproofed planter being back-filled. BOTTOM: Finished project.



CRS specializes in the restoration and repair of building exteriors and parking garages.