



PROJECT PROFILE

PROJECT:

Park Side Tower
Salt Lake City

COMPLETION DATE:

Fall of 2004

OWNER:

Cottonwood Property Management
Salt Lake City

Facility:

The Park Side Tower is located in downtown Salt Lake City.

Problem:

The curtain walls of the exterior of the building were allowing water to penetrate to some of the occupied offices. Numerous attempts by other contractors had been made to try to correct the problem with limited success.

Solution:

CRS installed a swing stage on the exterior of the building and used low-pressure water to test the walls and windows to determine where the water was entering. Upon discovery, the unfilled cracks and voids were filled with a urethane caulking to stop the water intrusion.

TOP RIGHT: Park Side Tower. CENTER: Swing stage used for inspection and repairs. BOTTOM: Completed repairs.

